



THIS BRACKET IS TO BE USED TO SUPPORT A MARBLE STONE .




To perform a stress analysis , I used fixed geometry at the slot region and applied the load on the pin which is con nected to the marble .

The contact set is used is bonded to make the bracket , pin and flat head bolt to act as one system



I am unable to solve this and I am getting following error.



MY QUESTION:

- 1) HOW TO RECTIFY THIS ERROR ??
- 2) What are the appropriate contact which should be used ??