




Maximum graphics with Zebra Stripes = Looks good from here.





With Curvature Colors Displayed: Zoomed out looks okay but zoom in a bit since the back edge of the blade has some colors to it, let's check that out closer.



Hmm, strange colors. Not sure it should show interrupted colors since it is a continuous curve, or rather it should be. And what the Hell is that “dog tag” of a surface doing there???



Sketch 6: Curvature combs on, looks suspicious to a trained eye.



Zoomed in to Clouded area: Sketch 6

I believe you need to draw the curve as a native Solidworks Curve as it is obviously not defined well. Try That.

When you zoom in to Lofted profile you see some bizarre surfaces have been generated. I believe this is causing you mesh problems. Check the other imported profile also.

